

MAXIMUM HUNTER boot MB3319

UPPER

High-quality full-grain leather, highly durable and wear-resistant. The TPU toe cap offers extra protection for the leather from impacts and abrasions. Equipped with a thickened TPU rear reinforcement for maximum heel stability and protection for the back of the foot.

CLOSING

Laces with extra strong eyelets and side zipper.

LINING

DRY PLUS in tight-weave polyester with extra protection in the heel area.

TOECAP

Fiberglass, lightweight and non-magnetic, offers high protection against impacts and compressions, ensures good thermal insulation.

PUNCTURE-PROOF

PS type composite, non-magnetic, antistatic, and thermal insulating. It offers maximum performance in terms of puncture resistance, full sole protection, and maximum flexibility.

FOOTBED

High-density polyurethane foam and Memory PU of variable thickness. The insert in the heel area provides a cushioning effect and ensures high shock resistance. Antistatic.

SOLE

The dual-component polyurethane and rubber offers excellent shock absorption. The nitrile rubber outsole, resistant to contact heat up to 300°C (HRO), ensures maximum grip on wet surfaces. The midfoot area is abrasion-resistant and equipped with lugs to increase grip on ladders, also complying with LG (Ladder Grip) certification. Furthermore, the outsole features deep, sharp-edged lugs for enhanced grip, and infinity-type lateral channels for liquid drainage. Self-cleaning.

FEATURES

ESD METAL FREE Designed for harsh environments with hydrocarbons and chemicals, uneven and particularly inaccessible terrain. The NEW MAXIMUM prove to be particularly robust and



wear-resistant. They offer cold insulation (CI) and heat insulation up to 150°C (HI). Suitable for: heavy industry, petrochemical and metallurgical industries, welding work, and work at height.

FIT

12

WEIGHT

890 g (size 42)

AVAILABLE COLOURS

● Z9 - Black

SIZES

 In stock
 On production
 Made to order
 Tailor made

FIELDS OF USE

- > Construction - road works
- > Light industry
- > Heavy industry
- > Petrochemical industry
- > Works at a height

MAINTENANCE

Store clean footwear in a cool and dry place, away from heat sources and protected from light. Footwear must be cleaned with soft-bristled brushes and water. Do not use chemical substances that could damage the materials.

QUANTITY PER CARTON

5

CATEGORY

II -> This product is currently planned and produced to comply with Regulation (EU) 2016/425 and subsequent modifications.