



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

| | | |
|----------------------------------|---------------------|---|
| Name: VERTEX helmet white | Code: FD2145 | FD21 FALL ARREST DEVICES - PETZL |
|----------------------------------|---------------------|---|

Description

Helmet made of ABS, polyamide, polycarbonate, high-strength polyester, polyethylene.
Equipped with a fabric harness with six-point fastening for maximum comfort. The DUAL chin strap allows the worker to modify the strength of the chin strap to adapt the helmet to different environments: work at height or work on the ground.
The CENTERFIT adjustment helps keep the helmet perfectly centred on the head, thanks to two lateral adjustment wheels. The FLIP&FIT system allows a low headband position to ensure an excellent helmet fit. The system retracts inside the helmet to facilitate storage and transport.
Shock absorption by deformation of the outer shell.
The closed outer shell protects against electrical hazards, molten metal projections and flames.
Headband: 53-63cm
Weight: 490g

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.



| | | |
|-----------------------------|--|---|
| Category III | Colours | Available Sizes In stock: U |
| Quantity/Carton 1 | EC Standards EN 397 EN 12492 EN 50365 | Important Information The helmet shall be worn in combination with the other tree climbing work-positioning devices. Read carefully the user sheet included. Make sure the item is in good condition, undamaged before use. Once you become aware of a damage, you should immediately replace it. Keep in a cool dry place, far from heat sources. Clean the shell with warm soapy water, then rinse with clear water. Donot use any solvents. |
| Dexterity | | Storage and cleaning |