



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015

Name: VERTEX HELMET RED	Code: FD2146	FD21 FALL ARREST DEVICES - PETZL
--------------------------------	---------------------	---

Description

Helmet with textile six-point harness for maximum comfort. CENTERFIT adjustment keeps the helmet perfectly centred on the head, thanks to the two lateral adjustment wheels. DUAL chinstrap clip allows the worker to modify the chinstrap resistance to adapt the helmet to different environments: working at height and working on the ground. The outer shell protects from electrical hazards, molten metal protections and flames.

The VERTEX helmet guarantees a very comfortable use, thanks to the six-points textile harness and the CENTERFIT and FLIP&FIT systems that guarantee an excellent hold of the helmet on the head. With an adjustable resistance chinstrap, it is suitable for work at height and on the ground. The closed outer shell protects against electrical hazards, cast metal projection and flames. The optimal integration of a Petzl headlamp, protective visor, noise shield and multiple accessories makes it a fully modular helmet that meets the additional needs of professionals.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.



Category III	Colours	Available Sizes U
Quantity/Carton 1	EC Standards EN 397 EN 50365	Important Information The helmet shall be worn in combination with the other tree climbing work-positioning devices. Read carefully the user sheet included. Make sure the item is in good condition, undamaged before use. Once you become aware of a damage, you should immediately replace it. Keep in a cool dry place, far from heat sources. Clean the shell with warm soapy water, then rinse with clear water. Donot use any solvents.
Dexterity		Storage and cleaning