



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: STRATO helmet black	Code: FD2161	FD21 FALL ARREST DEVICES - PETZL
----------------------------------	---------------------	---

Description

Helmet made of ABS, EPP, EPS, polyamide, polycarbonate, high-strength polyester, polyethylene.
Equipped with a DUAL chinstrap that allows the worker to modify the strength of the chinstrap to adapt the helmet to different environments: work at height or work on the ground. The closed outer shell protects against electrical hazards, projection of molten metal and flames. Shock absorption occurs by deformation of the expanded polystyrene inner shell.
The CenterFit adjustment system adjusts the headband to centre the helmet well on the head and for better stability.
Headband: 53-63 cm
Weight: 350 g.



- The case is equipped with:
- Side slots for mounting noise protectors.
 - Inserts to accommodate a protective visor.
 - Slot for mounting a headlamp.
 - Four positioning hooks for mounting a headlamp with elastic headband.

Equipped with resistance to lateral deformation LD and molten metal splash MM, electrical insulation 440V a.c. and resistance to low temperatures down to -10°C.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

Category III	Colours	Available Sizes Made to order: U In stock:
Quantity/Carton 1	EC Standards EN 397 EN 12492 EN 50365	Important Information To be used in conjunction with the other work-positioning devices in confined spaces. Read carefully the user sheet included. Make sure the item is in good condition, undamaged before use. Once you become aware of a damage, you should immediately replace it. Keep in a cool dry place, far from heat sources. Clean the shell with warm soapy water, then rinse with clear water. Do not use any solvents.
Dexterity		Storage and cleaning