



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciaci, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015
UNI EN ISO 45001:2018

Name: Gas alert MAX XT II CALIBR KIT + CASE	Code: FG110037	FG11 ELECTRICAL DEVICES GAS DETECTORS
----------------------------------------------------	-----------------------	----------------------------------------------

Description

Gas Alert Max XT II with carrying case and calibration kit, detects up to 4 gases simultaneously (Fuels, Oxygen, Sulphuric Acid, Carbon Monoxide). Included in the case: gas detector, batteries, anti-shock casing, calibration gas cylinder, demand flow regulator and the 3 m sampling tube.

Gas Alert Max XT II constantly shows the gas concentration on the display and it features:

- Full function self-test of sensor, battery status, circuit integrity and audio/visual alarms.
- Integrated sampling pump with a 3 m hose for gas detection in confined spaces.
- Impact and water resistant casing.
- Advanced microprocessors, and easily plug in/replaceable catalytic and electrochemical sensors.
- Low, high, TWA (Time Weighted Average), STEL (Short Term Exposure Limit) alarm for toxic gases and OL (Over Limit) alarm for combustible gases, low battery.
- Acoustic (95dB), visual and vibrating alarm.
- Rechargeable batteries.
- Compact 13.1 x 7.0 x 5.2 cm.
- Weight 328 g.



ATEX CERTIFICATION

Category	Colours	Available Sizes Made to order: U In stock:
Quantity/Carton 1	EC Standards EN 60079-0 EN 60079-11 EN 60079-26	Important Information Suitable to detect the presence of Fuels, Oxygen, Sulphuric Acid, Carbon Monoxide. Make sure the product is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. Keep in a cool dry place, far from heat sources.
Dexterity		Storage and cleaning