

Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441 export@sirsafety.com www.sirsafety.com





Name: RUSH jacket Code: MC2514H1 MC25 CLOTHING - HARDWEAR SERIES

Description

Advanced multi-pocket work jacket made of 80% Polyester, 20% Cotton, Twill, weight 300 g/m . Solid, stain resistant, quick drying and water repellent.

 High-performance triple stitched seams, bar-tacked for increased strength;

ËÁP^æç^Ás*c°ÁŸSSíÁsA^}dæÁA^|ÆB[ç^¦^åÁā]]^¦Ás∥[•*¦^L

EV [Á@^^Eaā ^}•ā} aþ&@•o∱[&\^o∱ā@haa Áx^|&|[íĒA;}^Á;-Á @&@ Áæá [aā^Á;@}^Á;@} Af. &\^o∱ā@haa Áx^|&|[íÆa;}^Á;-Á other with detachable ID badge holder and hidden zippered vertical pocket;

ËÁV, [Á, ˇ~Á,[&\^o•ÉÁ,}^Án]æ&ã(ˇ•Á5,}^kÁ,[&\^oÁ&|[•^åÁ,ão@Áx^|&\[íL

- Wear-and-tear reinforcements at the elbow;
- Elasticated inside cuffs, button-adjustable;
- Fleece-lined collar for maximum comfort;
- Adjustable waistband with side buttons;
- Reflex labels for extra visibility in low light conditions;
- 3Tí Án^-∤^& cãç^Ánd 引引*Áæe[ˇ} åÁ&@ cÊæe (Áæ) åÁn, ç^¦Ás@ Án @ ˇ |å^ |• Án Áa Áa highly visible when bending down;

ËÁV^•c^åÁ(¦Á@ed{~|Á~`à•cæ)&^•Áæ&&[¦åã]*Á(ÁU^\[ËV^¢íÁÛcæ)åæåÁ100;

- Industrial washable ISO 15797:2002.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 3*:

- Á0.80 m fluorescent material;
- Å0.20 m retro-reflective material.

*If combined with the trousers Art. mc2511.



Category	Colours	Available Sizes
II	HI-VIS ORANGE	In stock: XS - L, 4X
Quantity/Carton	EC Standards EN ISO 20471 Class:3	Important Information General and Road Constructions, Road sign work, Road and plants maintenance, Emergency response companies.
		The performance of the garment are guaranteed when it is correctly worn and fastened.
10		Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.
		We recommend to follow the washing instructions. Resistance up to 50 domestic washings.
Dexterity		Storage and cleaning