



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

export@sirsafety.com  
www.sirsafety.com



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015

<b>Name: VERTEX HELMET YELLOW</b>	<b>Code: FD2144</b>	<b>FD21 FALL ARREST DEVICES - PETZL</b>
-----------------------------------	---------------------	---

**Description**

Helmet made of ABS, polyamide, polycarbonate, high strength polyester and polyethylene.

The VERTEX helmet guarantees a very comfortable use, thanks to the six-points textile harness and the CENTERFIT and FLIP&FIT systems that guarantee an excellent hold of the helmet on the head.

CENTERFIT adjustment keeps the helmet perfectly centred on the head, thanks to the two lateral adjustment wheels. DUAL chinstrap clip allows the worker to modify the chinstrap resistance to adapt the helmet to different environments: working at height and working on the ground. The outer shell protects from electrical hazards, molten metal protections and flames.

The optimal integration of a Petzl headlamp, protective visor, noise shield and multiple accessories makes it a fully modular helmet that meets the additional needs of professionals.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.



Category <b>III</b>	Colours	Available Sizes <b>U</b>
Quantity/Carton  <b>1</b>	EC Standards EN 397  EN 50365	Important Information The helmet shall be worn in combination with the other tree climbing work-positioning devices.  Read carefully the user sheet included. Make sure the item is in good condition, undamaged before use. Once you become aware of a damage, you should immediately replace it.  Keep in a cool dry place, far from heat sources. Clean the shell with warm soapy water, then rinse with clear water. Donot use any solvents.
Dexterity		Storage and cleaning