

Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441 **TECHNICAL SHEET**

export@sirsafety.com www.sirsafety.com





Name: PLATINUM SHOE

Code: MB1824Z9 N

24Z9 MB18 FOOTWEAR - TOTAL PLANE SERIES

Description

Dissipative shoe, ankle-high model, with composite toecap and midsole, having a constant thickness of 4 mm. Extra strong nubuck leather upper. S3.

REACTOR SOLE: (PU/TPU) The wide cell polyurethane sole assures a very high shape memory effect. The TPU outsole assures long life, extreme mechanical resistance, flexibility, softness and hydrocarbon resistance. It has been designed with continuous horizontal grooving that supports flexion and foot movements. SRC slip resistant.

insole: Cross-foam insole made with solid material in polyurethane foam with variable thickness: 2.5 mm at the front and 9 mm in the heel area. Lined and perforated in the plantararea with outstanding anti-shock properties. Antistatic.

The 3D-TEX polyester lining has a high draining power thanks to the highabsorbent capacity of its fabric and its structure.

Main features:

- The wide fit, the conformation of the flat sole with 100% adhesion to the ground and the softness that gives the polyurethane to wide cells, improve comfort, reduce fatigue and increase efficiency.

- The additional overcap protects the shoe from shocks.

- Recommended on smooth and uniform surfaces.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

Category	Colours	Available Sizes
II	BLACK	39, 47
Quantity/Carton	EC Standards EN ISO 20345 EN 61340 EN 61340	39, 47Important InformationIndustrial plants, Construction and Road WorkSites, Logistics and Handling.Keep the footwear dry and clean in an appropriate environment at ambient temperature. The wet footwear should never be placed in direct contact with a heat source after use, but shallbe air-dried in a ventilated environment at ambient temperature.Make sure footwear is in good condition, before use. If the shoes are damaged, replace them.Clean the footwear with a soft brush and water. Do not use any substance such as alcohol, methyl ethyl ketone, thinners, gasoline, petrol or any other type of chemicals that could damage the materials,
Dexterity		the original protective features. Storage and cleaning

