



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



UNI EN ISO 9001:2015
UNI EN ISO 14001:2015

Name: VELVET SHORT JACKET	Code: MC3616H1	MC36 HIGH VISIBILITY CLOTHING - WINTER
----------------------------------	-----------------------	---

Description

High visibility short jacket made of Velvet fustian fabric 60% cotton and 40% polyester, weight 350 g/m . It features a shirt collar, concealed zipper closure with Velcro, two chest pockets with flap and Velcro, one of which is three-dimensional and equipped with a pen holder. High resistance jointed double seams. Double reflective bands on the bottom of the jacket and sleeves.

- The Velvet range offers high visibility requirements and guarantees cold resistance and insulation.
- The compact fabric retains body heat and its surface enhances the ability to repel liquid and dirt.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 2:

- 0.50 m fluorescent material;
- 0.13 m reflective material.

The article is certified according to EN ISO 20471 class 3 when used in combination with the following products:
MC3521, MC3522, MC3540, MC3543, MC3544, MC3612, MC3615

certified



Category II	Colours HI-VIS ORANGE	Available Sizes Made to order: 66 - 70 In stock: 44 - 64
-----------------------	---------------------------------	---

Quantity/Carton 20	EC Standards EN ISO 20471 Class:2	Important Information General and Road Construction, Road sign work, Road and plants maintenance, Service and assistance companies, Emergency response companies. The performances of the garment are guaranteed when it is correctly worn and fastened. Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. We recommend to follow the washing instructions. Resistance up to 50 washings.
------------------------------	--	---

Dexterity	Storage and cleaning
------------------	---------------------------------