

Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 Fax +39 02.90394441 export@sirsafety.com www.sirsafety.com





Name: STARMAX jacket

Code: MC3914HD

MC39 HIGH VISIBILITY CLOTHING - WINTER KNITWEAR

Description

High Visibility Softshell in 100% polyester 144 filaments TPU-laminated, bonded with 100% polyester 144 filaments microfleece, 335g/m Central zipper closure, bottom part of the jacket adjustable with drawstring and detachable hood with zipper and drawstring; detachable sleeves with zipper, cuffs adjustable with Velcro, two muff pockets with zipper closure and chest pocket with

zipper.Heat-sealed segmented reflective band on shoulders, chest and sleeves.

Three different overlapping layers in Softshell fabric create a unique combination that guarantees high levels of comfort: the polyester microfleece inner layer makes the fabric soft andwarm, the TPU membrane coupled with the polyester outer fabric allows moisture transpiration and thermoregulation, always keepingthe body dry, and making the garment windproof and storm-proof.

The product has been designed and manufactured to comply withRegulation

(EU) 2016/425 and subsequent amendments.

EN ISO 20471

Class 2:

Dexterity

= 0.50 m fluorescent material;

= 0.13 m reflective material.

V@Á(æã)Án¢¢^¦}æþÁææà¦&ZÁÁEÁÚÒSUËVÒÝíÁÚæa)åæèåÁF€€Á certified





Category	Colours	Available Sizes
II	HI-VIS ORANGE/BLUE	In stock: S - 4X
Quantity/Carton	EC Standards	Important Information
	EN ISO 20471 Class:2	General and Road Construction, Road sign work, Road and plants maintenance, Transport, Logistics, Service and assistance companies, Emergency response companies.
		Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.
		We recommend to follow the washing instructions.

Storage and cleaning