



SAFETY SYSTEM®
YOUR PROTECTOR

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575
Fax +39 02.90394441

TECHNICAL SHEET

export@sirsafety.com
www.sirsafety.com



Name: FLAME RETARDANT JACKET	Code: MC5414H5	MC54 CLOTHING - FLAME RETARDANT SERIES
-------------------------------------	-----------------------	---

Description

Jacket in 100% Flame Retardant cotton fabric, weight 315 g/m . It features a Chinese collar fastened with Velcro to protect the neck. Concealed front zipper closure with metal snap buttons; two side pockets and one chest pocket all with flaps and snap buttons, elasticated cuffs.

THE JACKET SHALL BE WORN IN COMBINATION WITH THE BIB-TROUSERS OR TROUSERS.

- It features remarkable multi-protective properties and is able to guarantee a high level of comfort while maintaining softness, lightness and breathability.
- it withstands up to 25 washes without altering the protective characteristics of the fabric.
- The full range can be produced upon order in orange and red colours.



Suitable for protecting the operator from accidental contact with minor flames, molten metal splashes, low values of convective and radiant heat, and accidental electric contact up to 100 V of short duration.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and it is classified as PPE Cat. II.

certified



Category II	Colours ORANGE	Available Sizes 38 - 70
-----------------------	--------------------------	-----------------------------------

Quantity/Carton 20	<p>EC Standards</p> <p>EN ISO 11611</p>  Class:1 Values:A1 <p>EN ISO 11612</p>  Limited Flame Spread:A1 Convective Heat:B1 Radiant Heat:C1 Molten Iron Splashes:E2 Contact Heat:F1	<p>Important Information</p> <p>Metalworking Industry, Metallurgical Industry, Foundries, Plastic materials processing, Gas, water and electricity Industries, Firefighting Teams.</p> <p>Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.</p> <p>We recommend to follow the washing instructions. Resistance up to 25 washings.</p>
---	--	--

Dexterity	Storage and cleaning
------------------	-----------------------------

