

|                                       |                       |  |
|---------------------------------------|-----------------------|--|
| <b>Name: POLYTECH Padded trousers</b> | <b>Code: MC576102</b> | <b>MC57 CLOTHING - POLYTECH SERIES</b> |
|---------------------------------------|-----------------------|--|

### Description

Trousers made of a technical fabric composed by 75% cotton, 24% polyester, 1% antistatic fibre fabric, weight 280 g/m, padding 100% aramid fibre 205 g/m, lining 50% aramid fibre 130 gr/m. It features a fly with zip and button, two front pockets with flap and Velcro, rear pocket with flap and Velcro, two three-dimensional functional pockets with flaps and Velcro on the legs. Featuring knee pad pockets.


THE TROUSERS SHALL BE WORN IN COMBINATION WITH THE JACKET

- The Polytech series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products.
- Thanks to its features it is multi-purpose, practical and resistant, breathable and comfortable.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425.

In combination with the coverall, is it possible to wear our under garments: Carboflame undershirt art. MC5610 and Carboflame underpants art. MC5620.



|                             |                            |   |
|-----------------------------|----------------------------|---|
| Category<br><b>III</b>      | Colours<br><b>TWO-TONE</b> | Available Sizes<br>Made to order: 40 - 70<br>In stock:  |
| Quantity/Carton<br><b>5</b> | EC Standards               | Important Information<br>Petrochemical Industry, Metalworking Industry, Refining Industry, Chemical Industry, Industrial Maintenance and Assemblies, Gas, Water and Electricity Mains Maintenance and Management, Oil & Gas industry.<br><br>Keep in a cool dry place, far from heat sources and direct light.<br>Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.<br><br>Keep in a cool dry place, far from heat sources and direct light.<br>Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it. |
| Dexterity                   |                            | Storage and cleaning<br>  |