



**export@sirsafety.com**  
**www.sirsafety.com**



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015  
UNI EN ISO 45001:2018

<b>Name: SUPERTECH 360 trousers</b>	<b>Code: MC5941ED</b>	<b>MC59 CLOTHING - SUPERTECH SERIES</b>
-------------------------------------	-----------------------	---

Trousers made of 80% cotton, 19% polyester, 1% dissipative fibre, weight 355 g/m . Equipped with a velcro hammer loop on waist, on left side. Featuring a front opening with zipper and hidden button, elastic waist band on the back side, two front pockets covered by technical holster pockets closed by flap and Velcro, with pen compartments and tool loops, 3 on the right side and 2 on the left side.

Equipped with a rear pocket closed with flap and Velcro, a pocket on left side with flap and Velcro and concealed PVC badge holder, double hanging ruler pocket on the right side, one of which closed by flap and Velcro, with tool loop.

Featuring two kneepadpockets with velcro fastening.

Double sewn reflective bands on the leg, 7 cm high.

- Supertech is flame retardant, antistatic, heat resistant, guarantees chemical protection and is high visibility.
- Its multi-purpose features also ensure comfort and breathability.







The product is designed and manufactured to comply with the requirements of Regulation (EU) 2016/425 and subsequent amendments.



V@Á æ Ácc^!} æÁæ!æÁ ÆÀÒSUËÒÝÍ Ææ æææÆÆÆ  
certified



Category III	Colours HI-VIS YELLOW/BLUE	Available Sizes In stock: 44 - 64
-----------------	-------------------------------	--------------------------------------

<p>Quantity/Carton</p> <p><b>20</b></p>	<p>EC Standards</p> <p>EN 1149-5</p>  <p>EN ISO 11611</p>  <p>Class:1 Values:A1</p> <p>EN ISO 11612</p>  <p>Limited Flame Spread:A1 Convective Heat:B1 Radiant Heat:C1 Molten Iron Splashes:E3 Contact Heat:F2</p> <p>EN ISO 20471</p>  <p>Class:2</p> <p>EN 13034</p>  <p>Type:PB[6]</p> <p>CEI EN 61482-2</p>  <p>APC:1</p>	<p>Important Information</p> <p>Read the instructions carefully before use. Store in a cool, dry place, away from heat sources and away from light. Before each use, carry out a visual check to ensure that the device is in perfect condition, undamaged and clean, and replace it if it is not intact. Garments offer protection only for the part of the body actually covered and must therefore be integrated, depending on the intended use, with suitable PPE to protect exposed parts of the body (head, hands, feet). Where necessary, use appropriate respiratory and eye protection. The safety features indicated are only respected if the device is regularly worn and fastened and in perfect condition.</p> <p>Follow the recommended washing instructions.</p>
<p>Dexterity</p>		<p>Storage and cleaning</p> 